

RECEIVED

MAR 15 1969

BROAD ST.
CALIBRATION LAB.

NAVWEPS 17-20AY-10
NAVSHIPS

Technical Manual

Instrument Calibration Procedure

AY-10

MICROWAVE CRYSTAL TEST SET
AIRBORNE INSTRUMENTS LABORATORY

TYPE

390-1 • 390-A2 • 390-A3

DEPARTMENT OF THE NAVY
BUWEPS-BUSHIPS CALIBRATION PROGRAM

Prepared By
Metrology Department, Pomona, California

PUBLISHED BY DIRECTION OF
THE CHIEF OF THE BUREAU OF NAVAL WEAPONS

30 JULY 1962

Reproduction for non-military use of the information or illustrations contained in this publication is not permitted without specific approval of the issuing service (BuWeps or AMC). The policy for use of Classified Publications is established for the Air Force in AFR 205-1 and for the Navy in Navy Regulations, Article 1509.

LIST OF CHANGED PAGES ISSUED

INSERT LATEST CHANGED PAGES. DESTROY SUPERSEDED PAGES.

NOTE: The portion of the text affected by the current change is indicated by a vertical line in the outer margins of the page.

* The asterisk indicates pages changed, added or deleted by the current change.

ADDITIONAL COPIES OF THIS PUBLICATION MAY BE OBTAINED AS FOLLOWS:

BuWeps

USAF ACTIVITIES.—In accordance with Technical Order No. 00-5-2.

NAVY ACTIVITIES.—Use Publications and Forms Order Blank (NavWeps 140) and submit in accordance with instruction listed thereon.

For listing of available material and details of distribution see Navsanda P-2002, Section 8 and NavWeps 00-500A.

PREFACE

This procedure has been prepared specifically for those laboratories participating in the Navy Calibration Program. The government assumes no responsibility for its use by other agencies.

The instruments utilized in this procedure were selected from those known to be at the disposal of the participating laboratories, and the listing by make and model number carries no implication of preference, recommendation, or approval by the Navy for use by other agencies. It is recognized that equivalent equipment produced by other manufacturers may be capable of equally satisfactory performance in the procedure.

TABLE OF CONTENTS

<u>Section</u>	<u>Title</u>	<u>Page</u>
1.	Introduction	1
2.	Equipment Required (or Equivalent)	1
3.	Meter Linearity and Voltage Divider Tests	2
3.1	Test Configuration	2
3.2	Meter Accuracy and Linearity Test	2
3.3	Voltage Divider Test	2
4.	Test Instrument Evaluation	3
	Navy Calibration Checklist	5

ILLUSTRATIONS

<u>Figure</u>	<u>Title</u>	<u>Page</u>
1.	Meter Linearity and Voltage Divider Test Connections	2

1. INTRODUCTION

1.1 This procedure describes the calibration of the type 390-1, 390A-2, or 390A-3 microwave crystal test set, which is a portable battery-powered instrument designed to measure the relative noise figure of microwave mixer crystals. The type 390A-3 microwave crystal test set may also be used to match crystals for use in balanced mixers, and to measure the relative sensitivity of microwave detector crystals. The instrument being calibrated will be referred to herein as the Test Instrument.

1.2 The Test Instrument consists of a 200 μ a meter, a 1.5 volt battery, and two voltage dividers.

1.3 Each Test Instrument function is tested to verify its correct performance within the required tolerances, as follows:

1.3.1 The Test Instrument panel meter is tested by checking the meter at each major-scale division. The test is performed by adjusting the variable control to obtain each major-scale division, and recording each corresponding indication from an external milliammeter connected in series with the Test Instrument.

1.3.2 The Test Instrument voltage divider is tested by establishing a voltage reference on the meter (the desired voltage reference is established when the meter indication equals the variable control indication), and switching in the voltage divider and recording the resulting meter indication.

1.4 All measurement data must be recorded on the calibration checklist, a sample of which is included in this procedure. Tests performed to verify Test Instrument operating characteristics should be noted on the checklist by placing checks in the spaces provided.

1.5 The estimated time for a routine calibration of the Test Instrument, excluding repair, maintenance, and unusual adjustment, is:

Setup time	0.1 hr
Calibration time	0.2
Total	0.3 hr

2. EQUIPMENT REQUIRED (OR EQUIVALENT)

NOTE

All instruments used during this calibration must bear current calibration servicing identification labels.

Substitute
Equipment

2.1 Decade resistor: GR 1432-N or Gray E-1044 MB

2.2 Milliammeter: Greibach 500, 1 μ a to 1 amp
Only the 0.3 and 0.1 milliamperage ranges are used in this procedure, or any ammeter capable of indicating currents from 30 to 225 μ a with an accuracy of $\pm 0.75\%$ or better.

Substitute
Equipment

2.3 Shielded phone plug: two conductor, standard size

2.4 Interconnecting leads as required

3. METER LINEARITY AND VOLTAGE DIVIDER TESTS

3.1 TEST CONFIGURATION

3.1.1 Connect all the applicable equipment as shown in figure 1.




Figure 1. Meter Linearity and Voltage Divider Test Connections

3.2 METER ACCURACY AND LINEARITY TEST

3.2.1 If necessary, adjust the Test Instrument and milliammeter mechanical zeros to zero the meters.

3.2.2 Set the decade resistor switches to obtain 1000Ω.

3.2.3 Set the milliammeter range switch to .3.

3.2.4 Set the Test Instrument variable control to 100.

3.2.5 Hold the Test Instrument CAL-TEST switch in the CAL position, adjust the variable control to obtain meter indications of 100, 80, and 60, and record each of the resulting milliammeter indications. Release the CAL-TEST switch.

3.2.6 Set the decade resistor switches to obtain 2500Ω, the milliammeter range switch to .1, and repeat step 3.2.5 for meter indications of 40 and 20.

3.3 VOLTAGE DIVIDER TEST

3.3.1 Adjust the Test Instrument variable control to exactly 100.

3.3.2 Set the milliammeter range switch to .3.

3.3.3 Hold the CAL-TEST switch to the CAL position, and adjust the decade resistor switches to obtain an indication of 200 on the milliammeter.

3.3.4 Hold the CAL-TEST switch to the TEST position, and record the milliammeter indication. Verify that the Test Instrument meter is indicating approximately 50, and release the CAL-TEST switch.

4. TEST INSTRUMENT EVALUATION

4.1 Complete the calibration checklist, and verify that the Test Instrument is in acceptable condition. If not, take the required corrective action in accordance with the instruction manual and local laboratory practices, and repeat the applicable portions of this procedure.

4.2 Unless other measurements are to be performed, disconnect the Test Instrument.

INTENTIONAL BLANK PAGE

NAVY CALIBRATION CHECKLIST
11ND-BWR-5512/9 (5-62)

SECTION A	1. CALIBRATING ACTIVITY	7. REASON FOR SUBMISSION
	2. SUBMITTING ACTIVITY	CERTIFICATION / CALIBRATION ☒ 1
	3. TEST INSTRUMENT <u>Crystal Test Set</u> (Name of Item Calibrated)	CROSSCHECK ☐ 2
	4. MANUFACTURER AIB	FAILURE FROM DAMAGE OR ABUSE ☐ 3
	5. MODEL NUMBER 390A-2 (Commercial or Military)	OPERATIONAL FAILURE ☐ 4
	6. SERIAL NUMBER	8. DATE OF LAST SERVICING
SECTION B	1. CALIBRATION TECHNICIAN	9. SERVICING CYCLE (MONTHS)
	2. TEST DATE	CERTIFICATION / CALIBRATION ☐
	3. CONDITION RECEIVED	CROSSCHECK ☐
	WITHIN TOLERANCE ☐ 1	
	OUTSIDE TOLERANCE ☐ 2 Explain Below in 'REMARKS'	
	4. CONDITION RETURNED	10. CALIBRATION PROCEDURE AY-10
WITHIN TOLERANCE ☐ 1		
OUTSIDE TOLERANCE ☐ 2 Explain Below in 'REMARKS'		
5. CERTIFICATED OR REPORTED VALUE, IF FIXED STANDARD	6. MAN-HOURS TO CALIBRATE	
	7. MAN-HOURS TO REPAIR (List Repairs in 'REMARKS')	
	8. SERVICING LABEL AFFIXED	
	CERTIFICATION / CALIBRATION ☐ 1	
	CROSSCHECK ☐ 2	
	LIMITED USE ☐ 3 (Explain Below in 'REMARKS')	
	REJECT ☐ 4	
	9. NEXT SERVICING DATE	
	CERTIFICATION / CALIBRATION	
	CROSSCHECK	
SECTION C	REMARKS	
Typical Calibration Checklist		
☐ REPLY TO REMARKS REQUESTED		APPROVED _____ LABORATORY SUPERVISOR

NOTE: GENERAL INSTRUCTIONS FOR COMPLETING THIS CHECKLIST ARE PROVIDED IN BUWEPSREP POMONA INST 4355.2

NAVY CALIBRATION CHECKLIST
11ND-BWR-5512/9 (5-62) (Back)

SECTION D

TEST INST(S): AIB 390-1, 390A-2, or 390A-3

PROC. NO.	MFR	MODEL	SER. NO.
AY-10			

[illegible]